

NOTICE OF TEMPORARY RELOCATION- KINZIE ELEMENTARY SCHOOL

August 26, 2026

Notice regarding the temporary relocation of students at John H. Kinzie Elementary School, located at 5625 S. Mobile Ave., Chicago, Illinois 60638, to John F. Kennedy High School, located at 6325 W. 56th Street, Chicago, Illinois 60638.

On or about August 10, 2026, CPS began monitoring potential mold concerns at John H. Kinzie Elementary School after CPS Facilities Operations received reports of peeling paint and possible mold in limited areas of the building. CPS referred the concerns to its Managing Environmental Consultant for assessment. On August 23, 2026, the Managing Environmental Consultant notified the CPS Facilities Team that some areas did not meet the mold clearance criteria, and remediation efforts began. The CPS Facilities Team is partnering with an independent environmental consultant and working with an independent environmental testing lab to ensure that all issues are addressed and that the school building is safe.

To ensure the continued safety of students and staff, Kinzie administration temporarily relocated students on August 24, 2026, to Kennedy High School, which is connected to Kinzie Elementary School via an indoor walkway. More information regarding this temporary relocation was detailed in a notice letter to parents and guardians of students.

The district is unable to comply with applicable requirements pursuant to 105 ILCS 5/34-200 through 5/34-235 due to the unexpected nature of this incident and potential imminent safety concerns. It further imposes restrictive timelines that would impede the school's ability to immediately address safety concerns. A copy of this Notice has been provided to the Principal, Local School Council, State Senator, State Representative, and Alderman.

The District has and/or will take the following steps in response to the concerns resulting in the temporary relocation:

- The CPS Facilities Team is partnering with an independent environmental consultant and working with an independent environmental testing lab to ensure that all issues are addressed and that the school building is safe.
- Deep cleaning classrooms and hallways.
- Operating dehumidifiers and air filtration devices in classrooms and hallways.
- Removing all ceiling tiles in the soffits, removing piping insulation, cleaning the interior of the soffits, re-insulating the pipe insulation and installing new ceiling tiles in the soffits of classrooms on the first floor.
- The Building Automation System (BAS) will be reviewed and optimized to enhance monitoring and operational control of applicable building systems.
- Installation of Halo Air Quality Monitors for real time monitoring of indoor air quality and alert system.
- Verification of all ventilation systems and repair of all drainage systems.

AVISO DE MUDANZA TEMPORAL

26 de agosto de 2026

Aviso sobre la mudanza temporal de los estudiantes de la Escuela Secundaria John H. Kinzie, localizada en 5625 S. Mobile Ave., Chicago, Illinois 60638, a la Escuela Secundaria John F. Kennedy, localizada en 6325 W. 56th Street, Chicago, Illinois 60638.

En o alrededor del 10 de agosto de 2026, CPS comenzó a inspeccionar la Escuela Primaria John H. Kinzie, respondiendo a preocupaciones de la presencia potencial de moho, tras haberse enviado al Departamento de Operaciones en Instalaciones informes de pintura pelada y posible moho en áreas limitadas del edificio. CPS refirió las preocupaciones a su consultor de manejo ambiental para obtener una evaluación. El 23 de agosto, el consultor de manejo ambiental notificó al equipo de Instalaciones de CPS que algunas áreas no satisfacían los criterios de ausencia de moho, y comenzaron los esfuerzos de remediación. El equipo de Instalaciones de CPS está colaborando con un consultor ambiental independiente y trabajando con un laboratorio de pruebas ambientales independiente para asegurar que se responda a todos los asuntos y que el edificio escolar sea seguro.

El 24 de agosto de 2026, la administración de Kinzie, para facilitar la seguridad continua de los estudiantes y el personal, mudó temporalmente a su estudiantado a la Escuela Secundaria Kennedy, que está conectada a la Escuela Primaria Kinzie por medio de una pasarela interior. Se incluyó más información sobre esta mudanza temporal en una carta de aviso enviada a los padres o tutores legales del estudiantado.

El Distrito no puede cumplir con los requisitos aplicables enumerados en las ordenanzas 105 ILCS 5/34-200 a 5/34-235, debido a la naturaleza inesperada de este incidente y los potenciales riesgos inminentes a la salud. Además, las ordenanzas imponen fechas restrictivas que obstaculizarían la capacidad de la escuela de responder de inmediato a asuntos de seguridad. Una copia de este aviso ha sido enviada a la directora y Concilio Escolar Local de la escuela, y al senador estatal, la representante estatal y el consejal asociados a la dirección de la escuela

El Distrito ha tomado o tomará los siguientes pasos en respuesta a las preocupaciones que resultaron en la mudanza temporal:

- El equipo de Instalaciones de CPS está colaborando con un consultor ambiental independiente y trabajando con un laboratorio de pruebas ambientales independiente para asegurar que todos los asuntos sean resueltos y que el edificio escolar sea seguro.
- Limpieza profunda de salones y pasillos.
- Operación de deshumidificadores y maquinaria de filtración de aire en salones y pasillos.
- Removido de todas las losetas de techo en los soffits, removido de la insulación en la tubería, limpieza del interior de los soffits, reemplazo de la insulación en la tubería, e instalación de nuevas losetas de techo en los soffits en los salones del primer piso.
- El sistema Building Automation System (BAS) será revisado y optimizado para mejorar el monitoreo y el control operacional de los sistemas del edificio aplicables.

- Instalación de monitores de calidad de aire Halo para lograr el monitoreo a tiempo real de la calidad del aire interior, y tener un sistema de alerta.
- Verificación de todos los sistemas de ventilación y reparación de todos los sistemas de desagüe.